



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 19, 2012

Reviewed: 

Mine Name: Eureka Rock	Permit Number: S/023/0094
Operator Name: Eureka Rock LLC	Inspection Date: March 29, 2012
Inspector(s): Wayne Western	Time: 4:10 – 4:30 pm
Other Participants: none	Mine Status: ACT
Weather Condition: Cool and overcast	Last Inspection: March 24, 2012
Bond Renewal Date: December 20, 2014	Bond Amount: \$20,800.00
Surface Ownership: Fee	Mineral Ownership: Fee
Last Year of Production: NA	Acreage: 4 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The permit and bond are current. The fees were paid on January 6, 2012. The annual report for 2011 was received on January 6, 2012. The Division had not received an annual report since 2006. If the Permittee did not conduct mining activities for 5 years then they could be required to reclaim the area. If no production occurs for ten years then reclamation is required unless an extension is granted by the Board.

Conclusions and Recommendations:

The Division should continue to monitor the site.

Directions to Site:

The site is east of Silver City.

Inspector's Signature



WHW:

cc: (OPERATOR)
agencies

O:\M023-Juab\S0230094-EurekaRock\inspections\INSP-03292012.doc



Propane tanks can be used for a landmark, site is east of the tanks



Highwall